Fig. 11: Mechanical cold-start accelerator (KSB), advance mechanism with automatic operation (cold-start position)

1 Clamp,
2 Bowden cable,
3 Stop lever,
4 Coil spring,
5 KSB advance lever,
6 Control device sensitive to coolant temperature.

